

TOP SECRET 093140Z MAR 68 CITE [] 0173 25X1A

25X1A [] INFO IMMEDIATE [] ROUTINE [] 25X1A

[] 25X1A

25X1A

A. EX6856

B. FILM EVALUATION REPORT

C. TYPE: 1A/3E00

D. FILM NO: 282/MX278/47" SEC/HZ DEGREES F./HAS 1.30-2AF 1.18

E. 1.80/2.1

F. 1404/2134/403-4-5-11-7

G. (1) GOOD

(2) NORMAL

(3) MEDIUM

(4) GOOD

(5) OPERATIONAL

(6) NORMAL

(7) 95 PERCENT CLOUD COVER NORTH VIETNAM 710 PERCENT CLOUD COVER

OVERALL MISSION.

25X1A

H. D.M. DISPOSITION TO []

1 DUPE POS TO NATIONAL CUSTOMERS

2 DUPE POS 2 DUPE NEG TO THEATER CUSTOMERS

25X1A

PAGE 2 [] TOP SECRET

1/3" TO 3/4" AITO FRAMES. 1/8TH OF FORWARD CLOCKS IN IMAGERY
 EVERY OTHER FRAMES APPROX 1/8" INTO FRAME. BACK ABRASSIONS 1"
 IN FROM TRAILING EDGE FROM 818 TO END OF MISSION. RECYCLING FROM
 956 THROUGH 974. PRESSURE MARKS ON BASE SIDE. STREAKS WERE NOTED ON
 BASE OF PART 411 5" INCHES IN FROM LEADING EDGE. MINUS DENSITY
 STREAKS IN FORWARD FRAMES NOTICABLE ONLY IN HORIZON ON FORWARD
 FRAMES. PLUS DENSITY STREAKS WERE APPARENT IN HORIZON ON FORWARD
 FRAMES RUNNING FROM LEADING TO TRAILING EDGE. FACTORY SPLICE IN
 FRAME 1102. PINHOLE IN 841 1/2" IN 1 3/4" FROM TITLING SIDE. PART 12
 HAD NUMEROUS HANDLING SCRATCHES THROUGHOUT. FRAME 842, 1066, 1252,
 1291 HAD NUMEROUS HANDLING SCRATCHES. 1304-1309 2 SCRATCHES 3
 INCHES IN 1/4" APART. FRAMES 121-125 WERE OVERLAPED. 1311, 1314
 HAD 9 STREAKS RUNNING VERTICAL. FRAMES 1304-1310 WERE FOG.

TOP SECRET

BT

Dcom